

Heat Transfer Foil Rolls for Fabric Foil Stamping

APPLICATION INSTRUCTIONS



310-350°F



5-10 Seconds



Low-Medium Pressure




Cold Peel

PRINTING INSTRUCTIONS

1. Print your design in black (CMYK) and follow the standard instructions of pressing A and B sheets together. Merry together sheets by following Forever Laser Dark or Image Clip Laser Dark Instructions.

- Print design on the blank side of the paper in REVERSE or in other words, flip it horizontally. This can be done within the design program or printer's settings (see your printer manual for more information).



2. Press your design onto your garment (after you have done Step 1 of applying adhesive) with the following time and temperature:

- Forever Laser Dark: 310 F° | 5-10 seconds | low pressure (2-3 bar) | Peel Cold
- Image Clip Laser Dark: 350 F° | 10 seconds | low-medium pressure (3 bar) | Peel Cold

APPLICATION INSTRUCTIONS

Pressing Foil Sheets

1. Place your foil sheet of your chosen color with the colored side face up (the back side should be lighter and more matte).

2. Cover with a silicone sheet and press with the following settings:

-Forever Laser Dark: 310 F° | 30-45 seconds | heavy pressure (5-6 bar)

-Image Clip Laser Dark: 350 F° | 30-45 seconds | heavy pressure (5-6 bar)