

# MagicTouch CPM 6.2

## APPLICATION INSTRUCTIONS

### PRINTING INSTRUCTIONS

Print from Multi-Bypass Tray  
Media Type Setting: Heavy

### APPLICATION INSTRUCTIONS

PRODUCT	PRESSURE	TEMPERATURE	TIME	PEEL TEMP	MIRROR
Uncoated Aluminum	Medium	340° F	80 sec.	Cold	Yes
Brass	Medium	340° F	80 sec.	Cold	Yes
Plastic	Medium	320° F	80 sec.	Cold	Yes
Acrylic	Light	320° F	120 sec.	Cold	No
Glass/ Crystal	Light	320° F	60-180 sec.	Cold	No
Corin	Medium	300° F	80 sec.	Cold	Yes
Stainless Steel	Medium	340° F	80 sec.	Warm	Yes
Magnet	Medium	300° F	80 sec.	Cold	Yes
Satin Ribbon	High	300° F	3-5 sec.	Hot	Yes
Book Covers	Medium	320° F	50 sec.	Cold	Yes
Pop Carboard	Medium	300° F	10 sec.	Hot	Yes
Ceramic	Light	300° F	180 sec.	Warm	Yes
Light Color Plaque Boards	Medium	340° F	60 sec.	Cold	Yes
Spectralight Boards	Medium	340° F	60 sec.	Cold	Yes
Leather (Light Color)	Medium	310° F	60 sec.	Warm	Yes
CD/ DVD/ BD	High	285° F	45 sec.	Warm	Yes
Nylon (Light Color-Non Washable)	High	310° F	10 sec.	Hot	Yes
Cardboard Box	High	310° F	45 sec.	Cold	Yes
Unfinished Wood (Matte Finish)	Medium	300° F	60 sec.	Hot, peel quickly	Yes
Finished Wood	Light	320° F	60 sec.	Warm	Yes
Coated Mugs	Medium	320° F	120 sec.	Cold	Yes
Anodized Aluminum	Medium	360° F	120 sec.	Cold	Yes

### TIPS

if a mistake is made during heat pressing, applied designs to most substrates can be cleaned away acetone and fabric / paper cloth.